

# CLIENT CASE STUDY



Complex onsite equipment was destructively decommissioned

## THE BUILDING

Our clients owned a complex meat processing facility. They were presented with a remediation issue and came to AssetWize to provide a factual evidence

Schedule provided with **remediation costs and clear structure**

## ASSETWIZE APPROACH

AssetWize created a detailed Scott schedule with full remediation costs and photographs within a clear structure

AssetWize provided evidence to **support successful negotiations**

## OUTCOME

The AssetWize report empowered the client's legal team to go into the negotiation armed with evidence to achieve a favourable outcome.